

Context	Command	Key Strokes	Primary Key
Ladder View (Edit)	Edit Not-Equal-To Contact	"!"	"!"
Ladder View (Edit)	Edit Less-Than Contact	"<"	"<"
Ladder View (Edit)	Edit Equal-To Contact	"="	"="
Ladder View (Edit)	Edit Great-Than-Or-Equal-To Contact	">"	">"
Ladder View	Select All	"Ctrl+A"	"A"
Data View	Sort Elements Ascending	"Ctrl+Shift+A"	"A"
Ladder View Data View Project Browser Documentation Editor	Copy into Clipboard	"Ctrl+C"	"C"
General	Open Documentation Editor	"Ctrl+D"	"D"
Data View	Sort Elements Descending	"Ctrl+Shift+D"	"D"
Ladder View	Toggle Edit Mode	"Ctrl+E"	"E"
Comment Editor	Goto Rung	"Ctrl+F"	"F"
Ladder View Documentation Editor XRef View	Open Find Dialog for that view	"Ctrl+F"	"F"
Ladder View Documentation Editor XRef View	Find Next in that view	"Ctrl+Shift+F"	"F"
Rung Comment Editor	Goto Rung	"Ctrl+G"	"G"
Ladder View (Edit)	Open Rung Comment Editor	"Ctrl+K"	"K"
General	Open Ladder View	"Ctrl+L"	"L"
General	Restore Default Window Layout	"Ctrl+Shift+L"	"L"
General	New Project	"Ctrl+N"	"N"
General	Open Project	"Ctrl+O"	"O"
Ladder View XRef View Documentation Editor	Print current View	"Ctrl+P"	"P"
Ladder View (Edit)	Replace Elements in Control Logic	"Ctrl+R"	"R"
General (Online)	Change PLC Mode	"Ctrl+Shift+R"	"R"
General	Save Project to Disk	"Ctrl+S"	"S"
General (Online)	Toggle View's Status On/Off	"Ctrl+Shift+S"	"S"
General	Edit Title Page	"Ctrl+T"	"T"
Ladder View (Edit) Data View Project Browser (Edit) Documentation Editor	Paste Clipboard into View	"Ctrl+V"	"V"
Ladder View (Edit)	Connect Wire to Output	"Ctrl+W"	"W"

Context	Command	Key Strokes	Primary Key
Ladder View (Edit) Data View Project Browser Logic Documentation Editor	Cut into Clipboard	"Ctrl+X"	"X"
General	Show Cross Reference View	"Ctrl+Y"	"Y"
Ladder View (Edit)	Undo Edit	"Ctrl+Z"	"Z"
Ladder View (Edit)	Delete Instruction to Left then Move Block Cursor to Left	Backspace	Backspace
Ladder View	Goto Previous Instruction	"Ctrl+Comma"	Comma
Ladder View (Edit) Data View Project Browser Logic Documentation Editor	Cut into Clipboard	"Ctrl+Delete"	Delete
Ladder View (Edit) Data View Project Browser Logic Documentation Editor	Delete	Delete	Delete
Ladder View (Edit)	Wire Down	"Ctrl+Down"	Down Arrow
Ladder View (Edit)	Delete Wire Down	"Ctrl+Shift+Down"	Down Arrow
Ladder View Rung Comment Editor	Goto Last Rung in Code-Block	"Ctrl+End"	End
Ladder View	Add Selection to End	"Ctrl+Shift+End"	End
Ladder View	Add Selection: Next Rung	"Shift+End"	End
Data View	Insert Element with Next ID	"Ctrl+Enter"	Enter
Ladder View (Edit)	Insert Row After Block Cursor	"Ctrl+Enter"	Enter
Data View	Structure Field: Insert Element with Next Field Structure: Insert Structure Elements	"Ctrl+Shift+Enter"	Enter
Ladder View (Edit)	Insert Row After Block Cursor, or Before Block Cursor when in first column	Enter	Enter
General	Launch Contextual Help Topic	F1	F1
Ladder View	Goto Element's Output Reference	F12	F12
Data View	Modify Element or Edit Cell	"Ctrl+F2"	F2
Ladder View (Edit)	Edit Positive Differential Powerflow Modifier	"Ctrl+F2"	F2
General (Online)	Open Change Value modeless dialog	"Ctrl+Shift+F2"	F2
Ladder View (Edit)	Edit Positive Differential Contact	"Shift+F2"	F2
Data View	Modify Element or Edit Cell	F2	F2
Ladder View (Edit)	Edit Normally Open Contact	F2	F2

Context	Command	Key Strokes	Primary Key
Trend View (Online)	Add/Remove Elements and other options	F2	F2
Ladder View (Edit)	Edit Negative Differential Powerflow Modifier	"Ctrl+F3"	F3
General	New Data View	"Ctrl+Shift+F3"	F3
Ladder View (Edit)	Edit Negative Differential Contact	"Shift+F3"	F3
Ladder View (Edit)	Edit Normally Closed Contact	F3	F3
Ladder View (Edit)	Open Contact Instruction Browser	F4	F4
Ladder View (Edit)	Open Coil Instruction Browser	F5	F5
Manual Output Mnemonic Entry dialog in Ladder View (Edit)	Open Coil Instruction Browser	F5	F5
Data View	Move to Format combo box	"Shift+F6"	F6
Data View	Move to Format combo box	F6	F6
Ladder View (Edit)	Open Box Instruction Browser	F7	F7
Manual Output Mnemonic Entry dialog in Ladder View (Edit)	Open Box Instruction Browser	F7	F7
Ladder View (Edit)	Accept Modified Rungs	F8	F8
Change Value dialog	Read Value from PLC	"Ctrl+F9"	F9
General	Read Project from PLC	"Ctrl+F9"	F9
Change Value dialog	Write Value to PLC	"Shift+F9"	F9
Data View	Write Value to PLC	"Shift+F9"	F9
General	Write Project to PLC	"Shift+F9"	F9
General	Open Element Browser	F9	F9
Ladder View Rung Comment Editor	Goto First Rung in Code-Block	"Ctrl+Home"	Home
Ladder View	Add Selection to Beginning	"Ctrl+Shift+Home"	Home
Ladder View	Add Selection: Previous Rung	"Shift+Home"	Home
Ladder View Data View Project Browser Documentation Editor	Copy into Clipboard	"Ctrl+Insert"	Insert
Ladder View (Edit) Data View Project Browser (Edit) Documentation Editor	Paste Clipboard into View	"Shift+Insert"	Insert
Ladder View (Edit)	Open Insert Rung, Row, Column dialog	Insert	Insert
Data View	Insert Row	Insert	Insert

Context	Command	Key Strokes	Primary Key
Project Browser	Open Create New Code-Block dialog	Insert	Insert
Ladder View (Edit)	Wire Left	"Ctrl+Left"	Left Arrow
Ladder View (Edit)	Delete Wire Left	"Ctrl+Shift+Left"	Left Arrow
Ladder View	Goto Element's Previous Reference	"Ctrl+Minus"	Minus
Ladder View	Zoom Out	"Ctrl+Shift+Minus"	Minus
Rung Comment Editor	Go 5 Rungs Forward	"Ctrl+PageDown"	Page Down
Ladder View (Edit)	Goto Next Modified Rung	"Ctrl+PageDown"	Page Down
Rung Comment Editor	Goto Next Rung	PageDown	Page Down
Print Preview	Next Page	PageDown	Page Down
Rung Comment Editor	Go 5 Rungs Back	"Ctrl+PageUp"	Page Up
Ladder View (Edit)	Goto Previous Modified Rung	"Ctrl+PageUp"	Page Up
Rung Comment Editor	Goto Previous Rung	PageUp	Page Up
Print Preview	Previous Page	PageUp	Page Up
Ladder View	Goto Next Instruction	"Ctrl+Period"	Period
Ladder View	Goto Element's Previous Reference	"Ctrl+Plus"	Plus
Ladder View	Zoom In	"Ctrl+Shift+Plus"	Plus
Ladder View (Edit)	Wire Right	"Ctrl+Right"	Right Arrow
Ladder View (Edit)	Delete Wire Right	"Ctrl+Shift+Right"	Right Arrow
Ladder View (Edit)	Wire Up	"Ctrl+Shift+Up"	Up Arrow
Ladder View (Edit)	Delete Wire Up	"Ctrl+Up"	Up Arrow